

FITNESS CERTIFICATE FOR SCHOOL BUILDING

1 Name of the Officer AKHIL G

2 Name of the School ST MONICA ENGLISH MEDIUM SCHOOL , KUMBLA

3 Location with Name of Education
Dist/ Sub Dist Kumbla, Kasargod

Classification of building as specified in column 4 of the application for Fitness Certificate Permanent

5	16.14 x 10.16 x 3.60	SF	01 Class room	1	37.76 x 10.16 x 3.60	RCC GF	06 class rooms
6	33.59 x 10.16 x 3.60	SF	04 Class room	2	33.59 x 10.16 x 3.60	RCC GF	06 class rooms
				3	37.76 x 10.16 x 3.60	FF	03 Class room and Auditorium
				4	33.59 x 10.16 x 3.60	FF	04 Class rooms

5 Period for which the certificate is issued 2021-22

6 Nature of defect N.A

7 a) Foundation and basement Laterite, RCC
b) Super Structure Laterite & RCC
c) Doors and Windows Country Wood
d) Wood work wrought and put up Country Wood
e) Roof RCC
f) Flooring Tiled flooring

8 Any major defects modified which will render the building unsafe in any manner No Defects

9 Whether maintenance works have been done properly Yes

10 Whether Structure is sound or not for Conducting class The above mentioned buildings are Found SAFE for conducting classes in Normal wind and weather conditions

I certified that the school building was inspected by me on 01/10/2021 and the above mentioned buildings only are found to be FIT to conduct class under Normal Weather condition

Place : Kumbla

Date : 01/10/2021

Assistant Engineer

(Signature)
Assistant Engineer
LID & EW Section
Kumbla Grama Panchayat

(Signature)
Manager
The Catholic Board of Education
Shanthy Kiran, Bajjodi
Mangalore - 575 005, INDIA



(Signature)
PRINCIPAL
ST. MONICA ENGLISH MEDIUM SCHOOL
CBSE CODE-931243
KUMBLA-671 321
Kasargod (Dist.) Kerala State